

Running 3.6 Fusion Software on Fusion II DVRs

Overview

The below guidelines must be followed to ensure 3.6 software functions properly on legacy Fusion II hardware.

Guidelines

- To be compatible with 3.6 software, Fusion II must be updated to Windows XP if currently running Windows 2000 Professional.
 - Fusion II XP Upgrade to Windows XP part number: HFW2KUPGWXP
- Equip IP camera connections are not supported on Fusion II hardware.
- Consistent with 3.5 Fusion server, Camera Sabotage Detection and Advanced Motion Detection remain disabled in 3.6 when running on Fusion II hardware.
- The following pre-existing Fusion II IP camera restrictions remain in effect after upgrade to 3.6.
 - Fusion II does not support MegaPixel network cameras
 - Fusion II is limited to 4ch of non-MegaPixel IP video
 - Fusion II non-Real Time 120ips DVRs do not support IP video

Honeywell

www.honeywellvideo.com
+1.800.796.CCTV (North America only)
HVSsupport@honeywell.com

Document XXX-XXXXX Rev A– 02/09

© 2009 Honeywell International Inc. All rights reserved. No part of this publication may be reproduced by any means without written permission from Honeywell. The information in this publication is believed to be accurate in all respects. However, Honeywell cannot assume responsibility for any consequences resulting from the use thereof. The information contained herein is subject to change without notice. Revisions or new editions to this publication may be issued to incorporate such changes. Specifications subject to change without notice. Imperial conversions are approximate.