

IP Cameras Supported by Fusion 3.7 Application Note

The following IP cameras are supported by the Fusion V3.7 DVR.

Honeywell IP Cameras

Honeywell KD6 VIP	HD6XXXND (where X is variable based on dome specs)
HCX Series Network Cameras	HF4CHSTRM
ACUIX™ IP PTZ Domes	EQUIP® Series Network Cameras
<ul style="list-style-type: none"> • ACUIX IP In-Ceiling • ACUIX IP Indoor Pendant • ACUIX IP Outdoor Pendant • ACUIX IP Rugged 	<ul style="list-style-type: none"> • HD4DIP • HCD554IP • HCS554IP

ACTi

ACTi+CAM5301	ACTi+CAM5321
ACTi+CAM7201	ACTi+CAM7301
ACTi+CAM7321	ACTi+CAM6510
ACTi+CAM6610	ACTi+CAM1431
ACTi+CAM1311	ACTi+CAM1100
ACTi+CAM3211	ACTi+CAM3311
ACTi+CAM3100	ACTi+CAM4100
ACTi+CAM2140	CAM-6500
CAM-6510	CAM-6610
CAM-6620	CAM-6630
ACM-8211	ACM-8511

Axis

All Axis cameras and network encoders with 3 digit model numbers running the 3.x.x.x and 4.x.x.x firmware versions.

V1 = 3.x.x.x	AXIS 205
AXIS 206, 206M, 206W	AXIS 209FD
AXIS 209FD-R	AXIS 209MFD
AXIS 210, AXIS 210A	AXIS 211, 211A, AXIS 211M, AXIS 211W
AXIS 212 PTZ	AXIS 213 PTZ
AXIS 214 PTZ	AXIS 215 PTZ
AXIS 216FD, AXIS 216FD-V, AXIS 216MFD, AXIS 216MFD-V	
AXIS 221	AXIS 223M

AXIS 225FD	AXIS 230
AXIS 231D+	AXIS 232D+

AXIS Video Servers

Brans

BNT 100	BNT 200
---------	---------

Sony

SNC-RZ25	SNC-RZ30
SNC-RZ50	SNC-RX550
SNC-P1	SNC-P5
SNC-Z20N	SNC-DF40N
SNC-DF70	SNC-CS3N
SNC-CS10	SNC-CS11
SNC-CS50	SNT-704
SNCD560N	SNCDF50N
SNCDM160	

Panasonic

BB-HCM381	WV-NM100
WV-NP472	

Samsung

SCC-C6475	
-----------	--

Lumenera

LE175C	
--------	--

Arecont Vision

AV2100	AV3130
AV1300	AV2000
AV3100	AV5100

Pixord

120/126	200/206
261	

Vivo Tek

IP6122	FD6112V
PT7135	VS3100P

Securgen

NE-VS100	NE-VS104
NE-VS400	

D-Link

DCS-2000	DCS-3220
----------	----------

DCS-5300	DCS-6620
----------	----------

DCS-900	
---------	--

Mobotix

M1M	
-----	--

Vantage

VIPS5301P	VIPS5321P
-----------	-----------

VIPS7201P	VIPS7301P
-----------	-----------

VIPS7321P	VIPS6510F
-----------	-----------

VIPS6610F	VIPS1431EP
-----------	------------

VIPS1311EP	VIPS1100E
------------	-----------

VIPS3211EP	VIPS3311EP
------------	------------

VIPS3100E	VIPS4100E
-----------	-----------

VIPS4100K	
-----------	--

Honeywell Systems Group (Head Office)

2700 Blankenbaker Pkwy, Suite 150
Louisville, KY 40299, USA
www.honeywellvideo.com
☎ +1.800.796.2288

Honeywell Systems Group Europe/South Africa

Aston Fields Road, Whitehouse Industrial Estate
Runcorn, Cheshire, WA7 3DL, UK
www.honeywell.com/security/uk
☎ +44.01928.754028

Honeywell Systems Group Pacific

Unit 5, Riverside Center, 24-28 River Road West
Parramatta, NSW 2150, Australia
www.honeywellsecurity.com.au
☎ +61.2.8837.9300

Honeywell Systems Group Asia

35F Tower A, City Center, 100 Zun Yi Road
Shanghai 200051, China
www.asia.security.honeywell.com
☎ +86 21.5257.4568

Honeywell Systems Group Middle East/N. Africa

Post Office Box 18530
LOB Building 08, Office 199
Jebel Ali, Dubai, United Arab Emirates
www.honeywell.com/security/me
☎ +971.04.881.5506

Honeywell Systems Group Northern Europe

Ampèrestraat 41
1446 TR Purmerend, The Netherlands
www.honeywell.com/security/nl
☎ +31.299.410.200

Honeywell Systems Group Deutschland

Johannes-Mauthe-Straße 14
D-72458 Albstadt, Germany
www.honeywell.com/security/de
☎ +49.74 31.8 01.0

Honeywell Systems Group France

Immeuble Lavoisier
Parc de Haute Technologie
3-7 rue Georges Besse
92160 Antony, France
www.honeywell.com/security/fr
☎ +33.(0).1.40.96.20.50

Honeywell Systems Group Italia SpA

Via della Resistenza 53/59
20090 Buccinasco
Milan, Italy
www.honeywell.com/security/it
☎ +39.02.4888.051

Honeywell Systems Group España

Mijancas 1. 3a planta
P.Ind. Las Mercedes
28022 Madrid, Spain
www.honeywell.com/security/es
☎ +34.902.667.800

Honeywell

www.honeywellvideo.com
+1.800.796.CCTV (North America only)
HVSsupport@honeywell.com

Document 800-04806 – Rev A – 07/09

© 2009 Honeywell International Inc. All rights reserved. No part of this publication may be reproduced by any means without written permission from Honeywell. The information in this publication is believed to be accurate in all respects. However, Honeywell cannot assume responsibility for any consequences resulting from the use thereof. The information contained herein is subject to change without notice. Revisions or new editions to this publication may be issued to incorporate such changes.