


Remote Connection to an HRDP DVR Using Windows® Vista and Internet Explorer Application Note

In the event that a **File access denied** message displays when connecting to an HRDP DVR with Internet Explorer in a Windows Vista operating system, you may find the instructions in this Application Note helpful.


Windows Vista contains a User Access Control (UAC) feature that can limit the installation of the HRDV Web Viewer in Internet Explorer. If this occurs, a message appears saying **File access denied**.



There are two ways to resolve this issue.

Option 1: Run Internet Explorer as Administrator

1. On your PC desktop, right-click the **Internet Explorer shortcut**.
2. Click **Run as administrator**.



If that does not resolve the issue, proceed to [Option 2: Disable User Account Control](#).

Option 2: Disable User Account Control

Note You will require Administrator rights to disable UAC. If you do not have a Windows User Account with Administrator privileges, please consult your IT department for assistance.

1. Open the Control Panel (**Start ► Control Panel**).
2. Double-click **User Accounts**. The User Accounts window appears.
3. Click **User Accounts**. A second User Accounts window appears.



4. Click **Turn User Account Control on or off**.
5. Deselect the **Use User Account Control (UAC) to help protect your computer** check box.



6. Click **OK**.
7. Click **Restart Now** to apply the change.
8. After your PC reboots, connect to the HRDP with Internet Explorer.

Honeywell Technical Support

For further support or if you have any questions, please contact Honeywell Technical Support.

Contact Information	For ...
Calling Honeywell in North America 1.800.796.CCTV	Honeywell Video technical support is available for help with training or to resolve technical issues.
Calling Honeywell outside North America See the back cover of this publication.	
E-mailing Honeywell HVSsupport@honeywell.com	Honeywell Video technical support can be reached by e-mail at the address on the left.
Whether you call or e-mail, please have on hand the information listed below:	
Your operating system	
The digital video recorder used	

Honeywell Systems Group (Head Office)

2700 Blankenbaker Pkwy, Suite 150

Louisville, KY 40299, USA

www.honeywellvideo.com

☎ +1.800.796.2288

Honeywell Systems Group Europe/South Africa

Aston Fields Road, Whitehouse Industrial Estate

Runcorn, Cheshire, WA7 3DL, UK

www.honeywell.com/security/uk

☎ +44.01928.754028

Honeywell Systems Group Pacific

Unit 5, Riverside Center, 24-28 River Road West

Parramatta, NSW 2150, Australia

www.honeywellsecurity.com.au

☎ +61.2.8837.9300

Honeywell Systems Group Asia

35F Tower A, City Center, 100 Zun Yi Road

Shanghai 200051, China

www.asia.security.honeywell.com

☎ +86 21.5257.4568

Honeywell Systems Group Middle East/N. Africa

Post Office Box 18530

LOB Building 08, Office 199

Jebel Ali, Dubai, United Arab Emirates

www.honeywell.com/security/me

☎ +971.04.881.5506

Honeywell Systems Group Northern Europe

Ampèrestraat 41

1446 TR Purmerend, The Netherlands

www.honeywell.com/security/nl

☎ +31.299.410.200

Honeywell Systems Group Deutschland

Johannes-Mauthe-Straße 14

D-72458 Albstadt, Germany

www.honeywell.com/security/de

☎ +49.74 31.8 01.0

Honeywell Systems Group France

Immeuble Lavoisier

Parc de Haute Technologie

3-7 rue Georges Besse

92160 Antony, France

www.honeywell.com/security/fr

☎ +33.(0).1.40.96.20.50

Honeywell Systems Group Italia SpA

Via della Resistenza 53/59

20090 Buccinasco

Milan, Italy

www.honeywell.com/security/it

☎ +39.02.4888.051

Honeywell Systems Group España

Mijancas 1. 3a planta

P.Ind. Las Mercedes

28022 Madrid, Spain

www.honeywell.com/security/es

☎ +34.902.667.800

Honeywell

www.honeywellvideo.com
+1.800.796.CCTV (North America only)
HVSsupport@honeywell.com

Document 800-04994 – Rev A – 08/09

© 2009 Honeywell International Inc. All rights reserved. No part of this publication may be reproduced by any means without written permission from Honeywell. The information in this publication is believed to be accurate in all respects. However, Honeywell cannot assume responsibility for any consequences resulting from the use thereof. The information contained herein is subject to change without notice. Revisions or new editions to this publication may be issued to incorporate such changes.